B.R No. 158/2013-14 Dated: 31.07.2013

Inspection report for the Work of: Construction of Moulded Drain in Kuvempunagara 1st Stage near Samudhaya Bhavan Roads in Ward No. 11 (Kuvempunagara), Vidyaranyapura Sub Division.

By,

Sri G.M. Muniyappa

Inspection Report

Name of Work	:	Construction of Moulded Drain in Kuvempunagara 1st Stage near Samudhaya Bhavan Roads in Ward No. 11 (Kuvempunagara), Vidyaranyapura Sub Division.
Work Order	:	EE/BTP/BBMP/E-TND/02(169)/WO/118/2012-13 Dated: 03.09.2012.
Agency	:	Hombe Gowda
B.R. No & Date	:	158/13-14 Dated: 31.07.2013
Bill Amount	:	10,48,811.52
Job Code	:	010-12-000055
P. Code	:	P-1771
Date of Inspection	:	01-07-15

The above said Work Construction of Moulded Drain in Kuvempunagara 1st Stage near Samudhaya Bhavan Roads in Ward (11) (Kuvempunagara) - has been Shown by the Concerned AE.

The above said Work has been Shown by the Concerned AE.

The Length of the Asphalted Road and Width of the Carriage width of the Road has been Checked by me and It is found Satisfactory

The depth of the Asphalted Road has been opened and the depth of the Bituminous layers has been Checked by me and It is found Satisfactory

The Measurements are Checked by me and It is found Satisfactory.

Executive Engineer
Byatarayanapura Division
Yalahanka Zone, B.B.M.P.
Bangalore-560092

G.M.MUNIYAPPA.
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

01/07/15

Sketch showing the Work of Construction of Moulded Drain in Kuvempunagara 1st Stage near Samudhaya Bhavan Roads in Ward No. 11 (Kuvempunagara), Vidyaranyapura Sub Division.



CC Road
- CC Drain
- Existing Drain Covering Slab
- Culvert
- Asphalt Road

Junior Engineer
Ward No. 11

Verified

G.M.MUNIYAPPA
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER
PUBLIC WORKS DEPARTMENT

04/07/15

Samudaya Bhavana

Photos for the Work of Construction of Moulded Drain in Kuvempunagara 1st Stage near Samudhaya Bhavan Roads in Ward No. 11 (Kuvempunagara), Vidyaranyapura Sub Division.

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(NTB)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Construction of Moulded Drain in Kuvempunagara 1st Stage near Samudhaya Bhavan Roads in Ward No. 11 (Kuvempunagara), Vidyaranyapura Sub Division.



G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Construction of Moulded Drain in Kuvempunagara 1st Stage near Samudhaya Bhavan Roads in Ward No. 11 (Kuvempunagara), Vidyaranyapura Sub Division.

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Construction of Moulded Drain in Kuvempunagara 1st Stage near Samudhaya Bhavan Roads in Ward No. 11 (Kuvempunagara), Vidyaranyapura Sub Division.



G.M.MUNIYAPPA
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Construction of Moulded Drain in Kuvempunagara 1st Stage near Samudhaya Bhavan Roads in Ward No. 11 (Kuvempunagara), Vidyaranyapura Sub Division.

G.M.MUNIYAPPA
B.E.(ELECT),B.E.(CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT